



Intel® Desktop Board D850EMV2 Specification Update

Release Date: November 2003

Order Number: A96647-008

The Intel® Desktop Board D850EMV2 may contain design defects or errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are documented in this Specification Update.

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER, AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT. INTEL PRODUCTS ARE NOT INTENDED FOR USE IN MEDICAL, LIFE SAVING, LIFE SUSTAINING APPLICATIONS.

Intel may make changes to specifications and product descriptions at any time, without notice.

Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them.

The Intel® desktop board D850EMV2 may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications before placing your product order.

Copies of documents which have an ordering number and are referenced in this document, or other Intel literature, may be obtained from:

Intel Corporation
P.O. Box 5937
Denver, CO 80217-9808

or call in North America 1-800-548-4725, Europe 44-0-1793-431-155, France 44-0-1793-421-777,
Germany 44-0-1793-421-333, other Countries 708-296-9333

Intel, Pentium, Celeron, and the Intel logo are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

* Other names and brands may be claimed as the property of others.

Copyright © 2002, 2003, Intel Corporation.

CONTENTS

REVISION HISTORY	v
PREFACE	vi
Specification Update for the Intel® Desktop Board D850EMV2	
GENERAL INFORMATION	3
SPECIFICATION CHANGES	5
ERRATA.....	8
SPECIFICATION CLARIFICATIONS.....	9



REVISION HISTORY

Date of Revision	Version	Description
June 2002	-001	This document is the first Specification Update for the Intel® Desktop Board D850EMV2.
August 2002	-002	Added Specification Change 1. Removed Printed Board Assembly (PBA) information from the document, as this reference is no longer valid.
September 2002	-003	Updated Legal Disclaimer Section.
October 2002	-004	Added Specification Change 2. Added Erratum 1.
December 2002	-005	Added Erratum 2, 3.
February 2003	-006	Added Specification Clarifications 1-4.
May 2003	-007	Added Specification Change 3.
November 2003	-008	Added Specification Clarification 5.

PREFACE

This document is an update to the specifications contained in the *Intel® Desktop Board D850EMV2 Technical Product Specification* (Order Number A94395). It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools. It will contain Specification Changes, Errata, Specification Clarifications, and Documentation Changes.

Refer to the *Intel® Pentium® 4 Processor Specification Update* (Order Number 249199) for specification updates concerning the Intel Pentium 4 processor and that may apply to the desktop board D850EMV2. Unless otherwise noted in this document, it should be assumed that any processor errata for a given stepping are applicable to the Altered Assembly (AA) revision(s) associated with that stepping.

Refer to the *Intel® 82850 Chipset Family: 82850/82850E Memory Controller Hub (MCH) Specification Update* (Order Number 298247) for specification updates concerning the 82850/82850E MCH Controller and that may apply to the desktop board D850EMV2. Unless otherwise noted in this document, it should be assumed that any MCH errata for a given stepping are applicable to the Altered Assembly (AA) revision(s) associated with that stepping.

Refer to the *Intel® 82801BA I/O Controller Hub (ICH) Specification Update* (Order Number 290677) for specification updates concerning the 82801 I/O Controller Hub and that may apply to the desktop board D850EMV2. Unless otherwise noted in this document, it should be assumed that any 82801BA I/O Controller Hub (ICH) errata for a given stepping are applicable to the Altered Assembly (AA) revision(s) associated with that stepping.

Nomenclature

Specification Changes are modifications to the current published specifications. These changes will be incorporated in the next release of the specifications.

Errata are design defects or errors. Characterized errata may cause the desktop board D850EMV2's behavior to deviate from published specifications. Hardware and software designed to be used with any given Altered Assembly (AA) and BIOS revision level must assume that all errata documented for that AA and BIOS revision level are present on all desktop boards.

Specification Clarifications describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in the next release of the specifications.

Documentation Changes include typos, errors, or omissions from the current published specifications. These changes will be incorporated in the next release of the specifications.

**Specification Update for the
Intel® Desktop Board D850EMV2**

GENERAL INFORMATION

Basic Desktop Board D850EMV2 Identification Information

AA Revision	BIOS Revision	Notes
A87192-401	MV85010A.86A.0025.P10	1-5
A87192-500	MV85010A.86A.0025.P10	1-5
A87951-402	MV85010A.86A.0025.P10	1-5
A87951-500	MV85010A.86A.0025.P10	1-5
A87990-401	MV85010A.86A.0025.P10	1-5
A87990-500	MV85010A.86A.0025.P10	1-5
A87993-401	MV85010A.86A.0025.P10	1-5
A87993-500	MV85010A.86A.0025.P10	1-5
A88970-401	MV85010A.86A.0025.P10	1-5
A88970-500	MV85010A.86A.0025.P10	1-5
C18361-603	MV85010A.86A.0053.P19	1-5
C18361-604	MV85010A.86A.0057.P20	1-5
C18369-604	MV85010A.86A.0053.P19	1-5
C18369-605	MV85010A.86A.0057.P20	1-5
C18701-603	MV85010A.86A.0053.P19	1-5
C18701-604	MV85010A.86A.0057.P20	1-5

NOTES:

1. The AA number is found on a small label on the component side of the board.
2. The 82850 Chipset kit used on this AA revision consists of three components as follows:

Device	Stepping	S-Spec Numbers
82850E MCH	A3	SL64X
82801BA ICH	B4	SL59Z
82802AB 4Mbit FWH	A1	SB48

3. Refer to the *Intel® Pentium® 4 Processor Specification Update* (Order Number 249199) for errata related to the Pentium 4 processor and that may apply to the desktop board D850EMV2.
4. Refer to the *Intel® 82850 Chipset Family: 82850/82850E Memory Controller Hub (MCH) Specification Update* (Order Number 298247) for errata related to the 82850/82850E MCH that may apply to the desktop board D850EMV2.
5. Refer to the *Intel® 82801BA I/O Controller Hub Specification Update* (Order Number 298242) for errata related to the 82801BA I/O Controller Hub that may apply to the desktop board D850EMV2.

Summary Table of Changes

The following table indicates the Specification Changes, Errata, Specification Clarifications, or Documentation Changes that apply to the desktop board D850EMV2. Intel intends to fix some of the errata in a future revision of the desktop board, and to account for the other outstanding issues through documentation or specification changes as noted. This table uses the following notations:

CODES USED IN SUMMARY TABLE

Doc:	Document change or update that will be implemented.
Fix:	This erratum is intended to be fixed in a future revision of the desktop board, driver, or BIOS.
Fixed:	This erratum has been previously fixed.
NoFix:	There are no plans to fix this erratum.
Shaded:	This erratum is either new or modified from the previous version of the document.

NO.	PLANS	SPECIFICATION CHANGES
1	Doc	Change to description of Table 14, Section 1.14.2.2, Fan Connectors
2	Doc	Support for faster Pentium® 4 processors
3	Doc	Support For Faster Intel® Pentium 4 Processors to Table 5 of Section 1.6 Processor
NO.	PLANS	ERRATA
1.	Fixed	Wake from an ACPI sleep state using wake methodologies may fail
2	NoFix	System boot time may be excessive when using ECC memory
3.	Fixed	Fan control defaults incorrectly set in BIOS for onboard hardware management ASIC
NO.	PLANS	SPECIFICATION CLARIFICATIONS
1	Doc	Addition to description of Section 1.7.1, Memory Features
2	Doc	Addition to description of Section 1.7.3, Continuity RIMM Modules
3	Doc	Addition to Section 1.13.1, Intel® Precision Cooling Technology for Advanced Fan Speed Control,
4	Doc	Addition to description of Section 1.10, Audio Subsystem
5	Doc	Clarification of SMBus Routing

SPECIFICATION CHANGES

The Specification Changes listed in this section apply to the *Desktop Board D850MV2 Technical Product Specification* (Order Number A94395). All Specification Changes will be incorporated into a future version of that specification.

1. **Change to Description of Table 14, Section 1.14.2.2, Fan Connectors**

Table 14, Section 1.14.2.2, will change in its entirety as follows:

Table 14. Fan Connector Descriptions for Boards that use the Hardware Monitoring and Fan Control ASIC

Feature	Processor Fan	Fan 1	Fan 2	Fan 3 (Note 1)
+12 V DC connection	Yes	Yes	Yes	Yes
Tachometer output	Yes	Yes	Yes	Yes
Controllable	No	Yes	Yes	Yes (Note 2)
Fan is on in the ACPI S0 or S1 states	Yes	Yes	Yes	Yes
Fan is off in the ACPI S3, S4, and S5 states	Yes	Yes	Yes	Yes

Notes: 1. This fan is present on the desktop board D850EMV2 only.

2. Fan 3 uses the same controls as fan 2. If fan 2 is switched off, fan 3 is also off.

2. **Support For Faster Pentium® 4 Processors**

Section 1.6, Processors will change in its entirety, as follows:

1.6 Processor



CAUTION

Use of unsupported processors can damage the board, the processor, and the power supply. See the Intel® Desktop Board D850EMD2/D850EMV2 Specification Update for the most up-to-date list of supported processors for these boards.

The desktop boards D850EMD2/D850EMV2 support a single Pentium® 4 processor (in a μ PGA478 socket) with a system bus of 400/533 MHz. Table 5 lists the supported processors.

Table 5. Supported Processors

Type	Designation	System Bus	L2 Cache Size
Pentium® 4 processor	Up to 2 GHz	400 MHz	256 KB
Pentium 4 processor	1.6A, 1.7A, 1.8A, 2A, 2.20, 2.40, 2.50, and 2.60	400 MHz	512 KB
Pentium 4 processor	2.26, 2.40B, 2.53, 2.66, 2.80 GHz	533 MHz	512 KB

The list of supported processors for the desktop boards D850EMD2/D850EMV2 is available from Intel's World Wide Web site. All supported onboard memory can be cached. See the processor's data sheet for cachability limits.

 **NOTE**

BIOS revision MV85010A.86A.0038.P15 or greater is required for the board to properly support 2.50 GHz Pentium 4 or later processors.

 **CAUTION**

Use only an ATX12V-compliant power supply with these desktop boards. ATX12V power supplies have two power leads that provide required supplemental power for the Intel® Pentium 4 processor and the Intel® 850E chipset. Always connect the 20-pin and 4-pin leads of the ATX12V power supply to the corresponding connectors on the board. Otherwise, the board and the processor could be damaged.

Do not use a standard ATX power supply. Doing so could damage the board and the processor.

For information about	Refer to
Processor support	Section 1.3, page 18
Processor usage	Section 1.3, page 18
Power supply connectors	Section 2.8.2.3, page 60

3. Support For Faster Intel® Pentium® 4 Processors to Table 5 of Section 1.6 Processor

Table 5 in section 1.6, Processor will change in its entirety as follows:

Processor Family	Processor Speed	System Bus	L2 Cache Size	BIOS Version	Notes
Pentium® 4 processor	3.06 GHz	533 MHz	512 KB	P21 or greater	The following board revisions (AA numbers) support these processors: C18361-601 or later C18369-601 or later. Please review the new http://developer.intel.com/design/motherbd/cooling.htm
	2.8 GHz	533 MHz	512 KB	P15 or greater	All board revisions support these processors
	2.66 GHz	533 MHz	512 KB	P15 or greater	
	2.6 GHz	400 MHz	512 KB	P15 or greater	
	2.53 GHz	533 MHz	512 KB	P10 or greater	
	2.5 GHz	400 MHz	512 KB	P15 or greater	
	2.4B GHz	533 MHz	512 KB	P10 or greater	
	2.4 GHz	400 MHz	512 KB	P10 or greater	
	2.26 GHz	533 MHz	512 KB	P10 or greater	
	2.2 GHz	400 MHz	512 KB	P10 or greater	
	2.0A GHz	400 MHz	512 KB	P10 or greater	
	2.0 GHz	400 MHz	256 KB	P10 or greater	
	1.9 GHz	400 MHz	256 KB	P10 or greater	
	1.8A GHz	400 MHz	512 KB	P10 or greater	
	1.8 GHz	400 MHz	256 KB	P10 or greater	
	1.7A GHz	400 MHz	512 KB	P10 or greater	
	1.7 GHz	400 MHz	256 KB	P10 or greater	
	1.6A GHz	400 MHz	512 KB	P10 or greater	
	1.6 GHz	400 MHz	256 KB	P10 or greater	
	1.5 GHz	400 MHz	256 KB	P10 or greater	
1.4 GHz	400 MHz	256 KB	P10 or greater		

ERRATA

1. ***Wake From an ACPI Sleep State Using Wake Methodologies May Fail***

PROBLEM: The desktop board hardware leaves the Resume Well Power OK (RSM_PWROK) signal deasserted before and after the resume well power (VccSus3_3 and VccSus1_8) is valid, instead of asserting it for 10 ms after valid power, which is required by the Intel® 82801BA I/O Controller Hub 2 (ICH2) and Intel® 82801BAM I/O Controller Hub 2 Mobile (ICH2-M) Datasheet (order number 290687). The result is that LAN wake attempts may fail.

NOTE: Wake from LAN* using the MagicPacket* utility will not be affected by this errata.

IMPLICATION: Users that take advantage of LAN wake methods to wake systems from an ACPI sleep state may experience some wake failures.

WORKAROUND: None.

STATUS: This issue was fixed in BIOS revision MV85010A.86A.0038.P15.

2. ***System Boot Time May be Excessive When Using ECC Memory***

PROBLEM: A blank screen may occur for as long as one minute during POST while the system is booting, when ECC memory is utilized.

IMPLICATION: When BIOS detects ECC memory during the system boot process, BIOS will run memory scans multiple times resulting in a delayed POST (up to one minute) making the system seem unresponsive.

WORKAROUND: None.

STATUS: This erratum will not be fixed.

3. ***Fan Control Defaults Incorrectly Set in BIOS for Onboard Hardware Management ASIC***

PROBLEM: Default BIOS settings on desktop boards that implement the Intel® Precision Cooling Technology fan control are incorrect, which could result in improper system cooling.

IMPLICATION: The maximum front and rear system chassis fan speeds are limited to 30% of maximum, irrespective of the actual chassis temperature. Under certain circumstances, this fan speed limitation may not provide adequate system cooling.

NOTE: The CPU fan is not controllable by the desktop board and is not directly impacted.

WORKAROUND: Disable fan control by changing the 'FAN CONTROL' setting to "Disabled" in the BIOS setup menu under the 'ADVANCED' tab, 'FAN CONFIGURATION' menu. This will allow the system fans to run at full speed, which will allow maximum system cooling.

STATUS: This erratum was fixed in BIOS revision MV85010A.86A.0057.P20.

SPECIFICATION CLARIFICATIONS

The Specification Clarifications listed in this section apply to the *Desktop Board D850MV2 Technical Product Specification* (Order Number A94395). All Specification Clarifications will be incorporated into a future version of that specification.

1. Addition to Description of Section 1.7.1, Memory Features

Section 1.7.1.1, Memory Features for D850EMVR will be added:

1.7.1.1 MEMORY FEATURES FOR D850EMVR

The desktop boards D850EMVR have four 2.5 V memory module sockets that support RIMMs containing Direct Rambus* DRAM (RDRAM) devices and support the following memory features:

- Maximum of 24 PC1066 RDRAM devices per channel (maximum 1.5 GB PC1066 onboard capacity utilizing 256/288 Mbit technology)
- Maximum of 32 PC800 RDRAM devices per channel (maximum 2 GB PC800 onboard capacity utilizing 128/144 Mbit or 256/288 Mbit technology)
- Single or double-sided RIMM modules
- Support for PC1066-32P compliant RDRAM with 533 MHz front side bus (FSB) operation
- Support for PC800-40 compliant RDRAM with 533 MHz FSB operation
- Support for PC800-40 and PC800-45 compliant RDRAM with 400 MHz FSB operation
- Serial Presence Detect (SPD) memory only
- ECC and non-ECC support

NOTE

These changes only affect desktop boards with AA numbers C18361–603, C18369-604, C18701-603, and later.

2. Addition to Description of Section 1.7.3, Continuity RIMM* Modules

Section 1.7.3.1, RDRAM Memory Configuration for D850EMVR will be added:

1.7.3.1 RDRAM Memory Configuration for D850EMVR

When installing memory, note the following:

- Install a pair of RIMMs in the sockets in bank 0 first. The RIMMs must be the same speed (PC1066-32P, PC800-40, or PC800-45), size (64 MB, 128 MB, 256 MB, or 512 MB), and density (single- or double-sided).

- If the desired memory configuration has been achieved in bank 0, install CRIMMs in the sockets in bank 1.
- If memory is to be installed in bank 1, the RIMM modules to be installed must be the same size and density to each other and match the speed of the RIMM modules in bank 0.

 **NOTE**

If bank 0 has two 128 MB RIMMs of PC800-40 RDRAM, bank 1 would require PC800-40 RDRAM also. However, any other supported RIMM modules such as 64 MB, 128 MB, 256 MB, or 512 MB could be used.

 **NOTE**

These changes only affect desktop boards with AA numbers C18361-603, C18369-604, C18701-603, and later.

3. Addition to Section 1.13.1, Intel® Precision Cooling Technology For Advanced Fan Speed Control

Section 1.13.1.4, Intel® Precision Cooling Technology for Advanced Fan Speed Control will be added:

1.13.1.4 Intel Precision Cooling Technology for Advanced Fan Speed Control

Intel Precision Cooling Technology automatically adjusts the chassis fan speeds depending on the system's temperature. This feature reduces system fan noise by lowering the speed of the chassis fans connected to the front, rear, and RIMM chassis fan connectors. This feature does not control the processor fan connector.

The fan speed control feature can be disabled in the BIOS, resulting in the chassis fans always operating at full speed. This feature should be disabled if a self-controlled fan is attached to a chassis fan connector.

Overall system noise reduction will vary based on system configuration and environment.

The features of the hardware monitoring and fan control ASIC (Analog Devices ADM1027, National Semiconductor LM85, Standard Microsystems SMSC EMC6D101, or equivalent) include:

- Internal ambient temperature sensor
- Two remote thermal diode sensors for direct monitoring of processor temperature and ambient temperature sensing

- Power supply monitoring of five voltages (+5 V, +12 V, +3.3 V, +1.5 V, and +VCCP1) to detect levels above or below acceptable values
- Fan monitoring for all fans (four fans on the Desktop Board D50EMVR)
- Thermally monitored closed-loop fan control, for all three fans, that can adjust the fan speed or switch the fans on or off as needed
- SMBus interface

For information about	Refer to
The location of the fan connectors and sensors for thermal monitoring	Figure 14, page 60
The Analog Devices ADM1027	http://www.analogdevices.com
The National Semiconductor LM85	http://www.national.com
The Standard Microsystems SMSC EMC6D101	http://www.smsc.com

NOTE

These changes only affect desktop boards with AA numbers C18361-603, C18369-604, C18701-603, and later.

4. Addition to Description of Section 1.10, Audio Subsystem

Section 1.10.1, Audio Subsystem for D850EMVR will be added:

1.10.1 Audio Subsystem for D850EMVR

The audio subsystem consists of the following devices:

- Intel® 82801BA ICH2
- Analog Devices AD1881b analog codec

The audio subsystem includes these features:


- Split digital/analog architecture for improved signal-to-noise (S/N) ratio: ≥ 85 dB
- Power management support for ACPI 1.0 (driver dependant)
- 3-D stereo enhancement

The audio subsystem supports the following audio interfaces:

- ATAPI-style connectors:
 - CD-ROM
 - Auxiliary line in

- Front panel audio connector, including pins for:
 - Line out
 - Mic in
- Back panel audio connectors:
 - Line out
 - Line in
 - Mic in
 - 1/8" stereo microphone back panel jack

Figure 8 is a block diagram of the audio subsystem.



OM12338

Figure 8. Audio Subsystem Block Diagram

For information about

The location and signal names of the back panel audio connectors

Refer to

Section 2.8.1, page 54

 **NOTE**

These changes only affect desktop boards with AA numbers C18361–603, C18369-604, C18701-603, and later.

5. Clarification of SMBus Routing

Section 2.8.2.1 will change in its entirety as follows:

2.8.2.1 Expansion Slots

The board has the following expansion slots:

- One AGP connector. The AGP connector is keyed for 1.5 V AGP cards only. Do not install a legacy 3.3 V AGP card. The AGP connector is not mechanically compatible with legacy 3.3 V AGP cards.
- PCI 2.2-compliant local bus slots (three on the desktop board D850EMD2; five on the desktop board D850EMV2). The SMBus is routed to PCI bus connector 2 only (ATX expansion slot 4). PCI add-in cards with SMBus support can access sensor data and other information residing on the board.
- One CNR connector (optional), shared with PCI bus connector 3 (ATX expansion slot 1) on the desktop board D850EMD2 or with PCI bus connector 6 (ATX expansion slot 1) on the desktop board D850EMV2.

NOTE

The SMBus routing to the PCI bus connectors does not conform to the PCI Engineering Change Notice (ECN) “Addition of the SMBus to the PCI Connector ECN”, dated October 5th, 2000. The ECN specifies that SMBus signals must be routed to all PCI bus connectors. On this board, SMBus signals are routed to PCI bus connector 2 only.

Add-in cards that implement PCI bus connector pins A40 and A41 for any purpose other than SMBCLK (SMBus clock) and SMBDAT (SMBus data) should not be installed in PCI bus connector 2.

For information about

Addition of the SMBus to the PCI Connector ECN

Refer to

http://www.pcisig.com/data/specifications/smb_ecn_0405_01.pdf

NOTE

This document references back panel slot numbering with respect to processor location on the board. The AGP slot is not numbered. PCI slots are identified as PCI slot #x, starting with the slot closest to the processor. The CNR slot shares PCI slot 6. The ATX/microATX specifications identify expansion slot locations

with respect to the far edge of a full-sized ATX chassis. The ATX specification and the board's silkscreen are opposite and could cause confusion. The ATX numbering convention is made without respect to slot type (PCI vs. AGP) but refers to an actual slot location on a chassis. Figure 15 on page 63 illustrates the desktop board D850EMD2's PCI slot numbering. Figure 16 on page 64 illustrates the desktop board D850EMV2's PCI slot numbering.