

Revision History of SETUPDS.EXE

6/29/1999

YAMAHA Corporation

Version 3.14 (6/29/99)

- Supports Intel i810 chipset (S-IRQ, PC/PCI).
- Possible to share an IRQ channel with other devices. (Set "IRQSHARE" to 1 in DS.INI.)

Version 3.13 (5/21/99)

- Fixed the problem that the DS-XG devices show "!" mark in the Device Manager on Win95/98 after executing setupds in MS-DOS mode.
- Enhanced the function to recover INTA# IRQ
- Added a variable "PIRQRC" in DS.INI to pre-assign an IRQ channel if it is known in advance.

Version 3.12 (4/28/99)

- Supports TSR
- Added a function to recover INTA# IRQ.
- Supports YMF754.

Version 3.11 (3/26/99)

- Supports SIS chipset (Except for S-IRQ).
- Supports D-DMA of VIA chipset (revision > 0x0B).
- Displays the Configuration Menu correctly in JP mode.

Version 3.10 (11/16/98)

- Supports VIA chipset.
- Improved the usage of the memory in Sound Blaster. (Fixed the problem that memory allocation error occurs on the system with specific CD-ROMs.)

Version 3.09 (9/17/98)

- Fixed the bug that DMA MODE cannot be changed with YMF724F, YMF738, YMF744.

Version 3.08 (9/17/98)

- Supports YMF738, YMF744.
- Fixed the bug that the system locks up when INTA# IRQ is assigned to the channel other than 5,7,9,10,11.

Version 3.07 (8/26/98)

- S-IRQ quiet mode can be supported. (Customization by DS.INI)
- Configures the DS-XG device even when the base memory address is 0x00000000.
- Can resume from the Power Down mode.
- Supports YMF737.

Version 3.06 (7/15/98)

- D-DMA can be used with 440BX + YMF724E.
- MIDI file can be played in the Sound Test. (FMMIDI.EXE and YMH.MID files are needed.)

Version 3.05 (5/20/98)

- Supports ALI chip set.
- Supports YMF724F, YMF740C.
- Can be terminated by CTRL+BREAK, CTRL+C.

Version 3.04 (4/16/98)

- Automatically detects A – C channel of PC-PCI.
- Supports YMF734.

Version 3.03 (3/30/98)

- Possible to use DS.INI which is not in the current directory.
- Uses +/- keys to change the volumes.

Version 3.02 (3/27/98)

- Cannot be executed in the DOS-Box. (Displays a warning message.)
- Does not configure the DS-XG device when the base memory address is 0x00000000. (Displays a warning message.)
- S-IRQ can be disabled. (Customization by DS.INI.)

- INTA# IRQ cannot be changed when INTA# IRQ is shared with other devices.

Version 3.01 (3/?/98)

- Added Sound Test function.

Version 1.00 (3/4/98)

- First official release.